

Container Loading Supervision Report

General Information:

Report Number	CLS-LCG23121303-TCLU6631681
Product Name	CONCRETE MIXER
PO No.	N/A
Ordered quantity	2 sets
Client name	---EJEMPLO---
Supplier name	---EJEMPLO---
Loading location	---EJEMPLO---
Loading date	XXXXXX
Container type	40HC
Container No.	TCLU6631681
Lock No.	CN43693AI



Inspection summary:

Inspection Sections	Result (Y / N / PENDING)	On-site Findings/Comments
1. Quantity & Assortment	Y	PASS
2. Packing & Shipping marks	PENDING	No packing
3. Random quality "spot-check"	Y	PASS
4. Condition of containers	Y	PASS
5. Loading process	Y	PASS
6. Measurements	Reference	reference



Conclusion:

PENDING FOR PART 2

Special Comments:

1. Factory NO weight bridge to check weight of truck & container.

Signature:

Manufacturer: Ren Ye Mei	LCG	Li Chuan Yong
	Inspector: 	

1. Quantity & Assortment:

Item #	Product Description	sets (Ordered)	Cartons (Ordered)	Cartons (Loaded)	Total Weight (Estimated)
N/A	STLT-3.5 SELF LOADING CONCRETE MIXER	2	/	/	8200kgs/set
Total:		2	/	/	8200kgs/set

Pictures:




2. Packing & Shipping marks


#	Checking item description	Result (Y / N/ PENDING)	On-site Findings/Comments
2.1	Condition of export cartons: no breaks, no damages	Y	PASS
2.2	Check the shipping marks on cartons/inner cartons.	PENDING	No information from the client
2.3	Bar code information included in shipping mark	N/A	N/A


Pictures: product











3. Random quality "spot-check":

#	Checking item description	Sample Size	Result (Y / N / PENDING)	Remark
3.1	Visual check (see if there's obvious visual problems)	2	Y	PASS
3.2	Function check (check the basic function)	2	Y	PASS

Pictures:

N/A	N/A
-----	-----

4. Condition of container(s):

#	Checking item description	Result (Y / N / PENDING)	On-site Findings/Comments
4.1	Dry and clean inside the container	Y	PASS
4.2	Free from bad odors inside the container	Y	PASS
4.3	Free from holes, cracks, or gaps	Y	PASS
4.4	Free of dents. If there are 2 or more dents, the depth of none of them should not exceed 15 mm.	Y	PASS
4.5	Free of deformation at the corner areas.	Y	PASS
4.6	Hinges/handles, closure devices are in good working condition	Y	PASS

Pictures: truck and container view







5. Loading process:

#	Checking item description	Result (Y / N/ PENDING)	On-site Findings/Comments
5.1.	No foreign material: except for the products in the packing list, any other material not allowed into the container	Y	PASS
5.2.	No cartons are damaged during the loading	Y	PASS
5.3.	If the container is sealed and locked	Y	PASS

Pictures:

Empty container	1/4 loading 1/3 part of machine loaded
	
2/4 loading 2/3 part of machine loaded	3/4 loading 3/3 part of machine loaded
	
Full loading	Close the container doors




Seal the container:

Locker details on the container door:



Model 1: disassemble to be 3 parts and fix in container







Model 2: unload container and load container from truck



6. Measurement's data sheet:

Test #	Testing items	Spec.	Sample #				
			1	2	3	4	5
6.1	Product size	N/A	760x280x 330cm	760x280x 330cm	/	/	/
6.2	Packing size: cm	No packing	/	/	/	/	/
6.3	G.W. of product: kg	N/A	8200	8200			
6.4	Container weight before loading: kg	N/A	/	/	/	/	/
6.5	Container weight after loading: kg	N/A	/	/	/	/	/

Pictures: size is estimated size





NIL






Other related pictures:

Weather: sunny



Loading location:



Factory Gate:



*******END OF THE REPORT*******

